Xymba USB DiscFlip: Disc failure rate is high

Reason 1:

Quality of the discs used.

Recommendation 1:

Check the brand and batch number of the discs used.

Â

Reason 2:

Drive lens is dying

Recommendation 2:

Contact your supplier

Â

Reason 3:

Discs are upside down?

Recommendation 3:

Check if discs are empty and if discs were placed into the loader correctly.

Â

Unique solution ID: #1029
Author: Acronova Tech Support
Last update: 2009-11-27 07:24

(c) 2024 John Doe <support@acronova.com>
URL: http://disc.acronova.com/kb/index.php?action=artikel&cat=18&id=30&artlang=en