Xymba USB DiscFlip: After launching the program a pop-up window appears showing error message.

Reason:

Finished Disc Bin is not in position on BW7160/XB47.
Output Ramp is not open on BW7161/XB57.

Â

Recommendation:

1.Check if the finished disc bin in sitting correctly in the XB47.
2. Check if the output ramp is open on the XB57.

Â

Unique solution ID: #1035
Author: Acronova Tech Support
Last update: 2009-11-24 04:47

(c) 2024 John Doe <support@acronova.com>
URL: http://disc.acronova.com/kb/index.php?action=artikel&cat=18&id=36&artlang=en