

Nimble Sidekick NK50Y System: Loud noise from NK50Y when disc caddy is moving

- â€¢ Make sure NK50Y, NB11 and Epson printer are being well placed
- â€¢ Make sure NK50Y is correctly attached onto Epson printer.
- â€¢ NK50Y may need hardware service. Contact technical support.

Unique solution ID: #1123

Author: Acronova Tech Support

Last update: 2010-11-02 10:14