

MyNK50V: Loud noise from NK50V when disc caddy is moving

â€¢ Make sure both NK50V and Epson printer are being well placed

â€¢ Make sure NK50V is correctly attached onto Epson printer.

â€¢ NK50V may need hardware service. Contact technical support.

Unique solution ID: #1084

Author: Acronova Tech Support

Last update: 2010-11-02 08:56