

Nimble Sidekick NK50V: Loud noise from NK50V when disc caddy is moving

- â€¢ Make sure both NK50V and Epson printer are being well placed
- â€¢ Make sure NK50V is correctly attached onto Epson printer.
- â€¢ NK50V may need hardware service. Contact technical support.

Unique solution ID: #1114

Author: Acronova Tech Support

Last update: 2010-11-02 10:00