

QQripper: Why does QQripper fail the initialization of autoloader?

Solution:

Make sure the autoloader and device drivers are successfully installed on the host computer. If it is power-off, close QQripper, turn on the power of the autoloader then re-launch QQripper. Refer to the "Inspecting the Autoloader Installation" section to see if the autoloader has been successfully installed.

Unique solution ID: #1057

Author: admin2

Last update: 2009-11-25 05:23