

*PC-Connected: After launching the program a pop-up window appears showing error message.*

**Reason:**

Finished Disc Bin is not in position on BW7160/XB47.  
Output Ramp is not open on BW7161/XB57.

Â

**Recommendation:**

1. Check if the finished disc bin is sitting correctly in the XB47.
2. Check if the output ramp is open on the XB57.

Â

*Unique solution ID: #1035  
Author: Acronova Tech Support  
Last update: 2009-11-24 04:47*